REY1S€D 5-7-87

FAILURE THOSE AND CAUSE Loss of Sync CMD Megative (TVC OFF) No Video No Control Worst Case: No PIU control of elbow camera to permit arm stowage Morst Case: The WA PIU cable is a 44-inch long, 25-wire assembly terminated by 37 pin co each end. The video and sync/cond wires are shielded Twinax shielded and twi of \$29 wire. The cable connects the TVC and PIU. Connector types KJ66E14N3 been selected. The cable design is taken from the successfully flown Apollo program. The dable-connector assembly in which the wire terminations are protected from e flexture at the joint between the wire and the connector terminal. The load concentration is moved away from the conductor connection and distributed ax the length of the conductors encapsulated in a potted-taper profile. This talso, protects the assembly from dirt and entrapped moisture which could caus in space. The cable and its components neet the applicable requirements of NASA, Milit specifications. These requirements include:	503 - <u>5</u>
Open/Short to GND Worst Case: No PIU control of elbow camera to permit arm stowage The cable design is taken from the successfully flown Apollo program. The date-connector assembly in which the wire terminations are protected from effecture at the joint between the wire and the connector terminal. The load concentration is moved away from the conductor connection and distributed as the length of the conductors encapsulated in a potted-taper profile. This talso, protects the assembly from dirt and entrapped moisture which could cause in space. The cable and its components neet the applicable requirements of NASA, Milit	
Seneral Mechanical Flactrical Features Design and Construction Materials Terminal Solderability Environmental Qualification Marking and Serialization Traceability and Documentation	sted pairs 55N16 have esign is a xcessive fally along echnique e problems

REVISEO 5-7-87

FREA NG. W 4.5.1 CRITICALITY 2/IR		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT Cable DNG NO. 2293287-503 1550ED 10-14-86 SHEET 2 OF 5	
FAILURE MOUE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE		
FAILURE MODE AND FAILURE EFFECT		QUALIFICATION TEST Qualified by 1.) similarity to previous successful spacualification tests of CCTV LRUs. ACCEPTANCE TEST The cable acceptance test consists of an ohometer checonnection is present and intact. Results are recorded operational TEST The following tests verify that CCTV components are of the PHS (A7A1) panel switch, through the RCU, through to the Camera/PTU command decoder are proper. The test ability to produce video, the VSU's ability to route a display video. A similar test verifies the MOM command Pre-Launch on Orbiter Test/In-Flight Test 1. Power CCTV System. 2. Select a monitor via the PHS panel, as destination source. 3. Send "Camera Power On" command from PHS panel. 4. Select "External Sync" on monitor. If video on stable raster), then this indicates that the came from the RCU and that the camera is producing synt. 5. Send Pan, Tilt, Focus, Zoom, ALC, and Gamma comman monitor or direct observation) verify proper oper Select Downlink as destination and camera under to Observe video routed to duwnlink. 6. Send "Camera Power Off" command via PHS panel. 7. Send "Camera Power Off" command via PHS panel. 8. Send "Camera Power Off" command via PHS panel. 9. Send "Camera Power Off" command via PHS panel. 10. Repeat Steps 3 through 9 except issue commands via proves that the CCTV equipment is operational if	ck to assure that each wire ed on data sheets. perable and that the commands from the sync lines to the Camera/PTU, sts also verify the camera's wideo and the munitor's ability to and path. on and the camera under test as monitor is synchronized {1.e., era is receiving composite synchronized video. Ids and visually jeither via the action. Its source.	
	I	1		

FREA NO. W 4.5.1 CRITICALITY 2/1R		SHUTTLE CCTV CRITICAL FIEMS LIST	UNIT CABLE DNG NO. 2293207-503 1550F0 10-14-86 SHEET 3 OF 5	
FATLURE MODE AND FATCURE EFFECT ON EAR ITEM		HATIONALE FOR ACCEPTANCE		
.bss of Sync CMD Negative (TVC OFF) pen/Short to GNO	No Yideo No Control Worst Case: No PTU cuntrol of elbow camera to permit arm stowage	QA/INSPECTION Procurement Control - Nire, connectors, solder, etc. are procured from approved wend and suppliers which meet the requirements set forth in the CCTV contract and Quality Plan Nork Statement (WS-2593176). Incoming Inspection & Storage - Incoming Quality inspections are made an all receive materials and parts. Results are recorded by lot and retained in file by drawing an control numbers for future reference and traceability. Accepted items are delivered Naterial Controlled Stores and retained under specified conditions until cable fabrication is required. Mon-conforming materials are held for Naterial Review Boar (MRB) disposition. (PAI-307, PAI IQC-51). Assembly & Test - Prior to the start of assembly, all items are verified to be correby stock room personnel as the items are accumulated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL). Specific instructions are given in assembly drawing notes and applicable documents called out in the Fabrication Procedure and Record (FPR-2293207). These are 2200000 Process Standard crimping flight connector contacts, 2280001 - Process Standard in-1 spilcing of standard interconnecting wire using Raychem solder sleeves, 2200076. Process Standard marking of parts or assemblies with epoxy colors, 2200076. Potting material and test procedure [PP-AT-2293207}, Quality and OCAS Inspections are perforant the completion of key operations. Preparation for Shipment - When fabrication and test is complete, the cable assembly packaged according to 2200746, Process Standard for Packaging and Handling Guideline All related documentation including assembly drawings, Parts List, ABPL, Fest Data, is yathered and held in a documentation folder assigned specifically to each cable assembly. This folder is retained for reference.		

			REV15ED 5-7-87
FMEA NO W 4.5.1 CRETICALITY		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT CAB (e PMG NO. 7299287-503 ISSUEO TO-14-86 SHEET 4 OF 5
FAILURE MODE AND CAUSE	FATLWIE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
Loss of Sync CMD Negative (TVC UFF) Open/Short to GNU	Na Videa Na Control	FAILURE MISTORY There have been no reported failures during RCA testing	, pre-flight or flight.
	Norst Case: No PTU control of elbow camera to permit arm stowage		•
			· · · · · · · · · · · · · · · · · · ·

43.660

REVISED 5-7-87

FNEA NO. <u>U 4.5.1</u> CRITICALITY 2/1R	·	SHUTTLE CCTY CRITICAL ITEMS LIST	UNIT Cable DWG NO. 2293207-503 1 \$\$UED TO-T4-86 \$HEER 5 OF 5	
FATENRE MODE AND CALISE	FATURE EFFECT ON END ITEN	RATIONALE FOR ACCEPTANCE		
Loss of Sync CMD Regative (TWC DFF) Open/Short to 6ND	No Video No Control Nurst Case: No PTU control of elbow camera to permit arm stowage	Loss of ability to position the Elbow camera. Possible inability to stow the SMS elbow camera physically interferes with a payload. If SMS cannot be stowed the propayload bay door cannot be closed. Loss of crew and vehicle. IREV ACTIONS Perform EVA to reposition the elbow camera, use RMS motion to reposition the camerication the RMS. CREW TRAINING Crew should be trained in contingency EVA and RMS operations procedures. MISSION CONSTRAINT Do not manifest Elbow camera for any flight where the payload and the elbow camerrinterfare with each other (for any pan or tilt angle). If the camera must be flooned change the camera position until the interfering payload is deployed.		